

Tachometers and Tach/Hourmeters – AT and ATH Series



* Products covered by this bulletin comply with EMC Council directive 89/336/EEC regarding electromagnetic compatibility except as noted.

The AT Series tachometers are rugged, transistorized instruments with solid-state circuitry for indication of engine RPM. They are equipped with a bracket for mounting into a standard 3-3/8 in. (86 mm) dash mounting hole. A full 270° sweep of the pointer gives an accurate indication on a large easy-to-read scale and the dial can be illuminated for night reading. The ATH Series models are also equipped with hourmeter to record the elapsed running time of an engine.

Models available for Alternator, Magnetic Sensor or Ignition signal These instruments are designed to function from pulses generated by an alternator with 4, 8, 12, 14, or 16 poles on the rotor. The pulses can also be obtained from the ring gear of an engine by means of an **electromagnetic sensor** (magnetic pickup). Murphy's magnetic sensor driven models are designed to function with flywheels having anywhere from 50 to 304 teeth. **Ignition signal** model available for 4, 6 or 8 cylinder, spark-ignited engines. All models are for negative ground, positive ground or isolated electrical systems and are protected against reverse polarity hookup.

All models are powered by a 11-28 VDC battery and are reverse polarity protected.

Series Models

ATS Series Magnetic Sensor Signal Tach

50 - 304 pulses^{*} 11-28 VDC, 2733 Hz to 13.62 kHz @ 4000 RPM

ATHS Series Magnetic Sensor Signal Tachometer/Hourmeter 50-304 pulses* 11-28 VDC, 2733 Hz to 13.62 kHz @ 4000 RPM

* To determine pulses per engine revolution, work the formulas on the back page and use the pulses per revolution number to determine if the tachometer can be used for your application.

ATA Series Alternator Signal Tachometer 3-27 pulses* 12 VDC, 137 to 1330 Hz @ 4000 RPM

ATHA Series Alternator Signal Tachometer/Hourmeter 3-27 pulses* 12 VDC, 137 to 1330 Hz @ 4000 RPM or 193 to 1815 Hz @ 4000 RPM

ATHI Series Ignition Signal Tachometer/Hourmeter 4, 6 or 8 cylinder engines @ 4000 RPM

Bezel Styles



Applications

These tachometers are specially designed for use on truck, marine, industrial, or stationary engines.

Dimensions



In order to consistently bring you the highest quality, full featured products, we reserve the right to change our specifications and designs at any time. MURPHY products and the Murphy logo are registered and/or common law trademarks of Murphy Industries, LLC. This document, including textual matter and illustrations, is copyright protected by Murphy Industries, LLC, with all rights reserved. (c) 2011 Murphy Industries, LLC.

How to Determine if the Tachometer or Tach/Hourmeter is Suitable for Your Equipment

- Α. Ignition sensing Tach/hourmeters can be used on 4, 6 or 8 cylinder, spark ignited engines.
- B Magnetic pick up sensing Tachometer or Tach/hourmeters will operate from 70 to 225 tooth flywheels.
- C. Alternator sensing Tachometer or Tach/hourmeters will operate from 3 to 27 pulses per engine revolution. To obtain the number of pulses per engine revolution, work the following formulas:
 - 1 Determine the number of poles on your alternator. Look for the designation/type in the manufacturer's manual or remove the pulley and fan to count the number of poles on the rotor.
 - The ALTERNATOR TACHOMETER CHART lists common 2. alternators and their minimum and maximum pulley ratios. Determine pulley ratio with the following formula:

PULLEY RATIO = CRANK SHAFT PULLEY DIAMETER

- Check that Pulley Ratio falls within the range shown on the 3. PULLEY RATIOS CHART for a particular alternator. If ratio falls in the shaded area, the tachometer can be calibrated for the application.
- To determine the pulses per engine revolution: 4.

NUMBER OF POLES × PULLEY RATIO = PULSES PER ENGINE REVOLUTION

Specifications

Power Input: 11-28VDC (70mA except lamp load).

- Back Light: 3 to 4W Bulb Wedge base
- RPM Input Signal Voltage: 1.5 Vrms min. from a magnetic pickup V low: 0.5V ma, V high: 8.0V min.from Alternator Driven and Ignition Switch
- Accuracy: Tachometer: ± 2% full scale

Hourmeter: +0.01% hours, +1 count.

Hourmeter: ± 0.01% hours, ± 1 count.

- Temperature Range: -40°C to +82°C (no permanent damage shall occur).
- Dial: 270° sweep white numerals (over black background)
- Bezel: 304 Stainless Steel for bright and IS 513 E.E.E. CRCA steel for black.

Scales: 0-4000 RPM.

Case Material: Plastic.

Hourmeter Range: 99999.9 hours in 0.1 increments

Shipping Weight: 0.89 lb. (403 g).

Shipping Dimensions: 5-1/2 x 5-1/2 x 5-1/2 in. (140 x 140 x 140 mm).

PULLEY RATIOS CHART RATIO -+ 0.5 1.5 20 25 30 35 40 45 50 Minimum Maximum 1.5 -- 13 4 OF POLES 0.75 -- 65 8 0.5 -- 4.3 12 214 0.42 -- 3.7 16 0.375 -- 3.25

ALTERNATOR TACHOMETER CHART				
Manufacturer	Designation/Type	Poles	Minimum pulley-ratio	Maximum* pulley-ratio
Prestolite	Al	8	0.75	6.5
Load Handler	88A, 8LHA, 89C, 8LHC	16	0.375	3.25
Load Handler	All 5 inch models	12	0.5	4.3
Leece Neville	Al	12	0.5	4.3
Bosch	G and K Series	12	0.5	4.3
C.E. Neihoff	All	12	0.5	4.3
Deico Remy	30DN	4	1.5	13
Delco Remy	15SI, 21SI, 40DN, 40SI	12	0.5	4.3
Delco Remy	10DN, 10SI, 12SI	34	0.42	3.7
Delco Remy	20DN, 25SI, 27SI	16	0.375	3.25
Delco Remy	2951.3051	16	0.375	3.25
Hitachi	LT125, LT130, LT133	8	0.75	6.5
Hitachi	LT150	12	0.5	4.3
Lucas	Al	12	0.5	4.3
Mando	Al	12	0.5	4.3
Motorcraft	Al	12	0.5	4.3
Nepondenso	Al	12	0.5	4.3
Powerline	Series 23	14	0.42	3.7
Powerline.	Series 24, 25, 26	12	0.5	4.3
Valeo	Al	12	0.5	4.3

How to Order

Order the Tachometer or Tachometer/Hourmeter by model number.

Magnetic Sensor	Tachometer 4000 RPM; 50 - 304 pulses 11-28 VDC
Model #	Designation
ATS-40-12	Bright Stainless Steel Bezel
ATS-40-12-A	Black Stainless Steel Bezel
ATS-40-12-B	SAE Bright Stainless Steel Bezel
ATS-40-12-C Magnetic Sensor	SAE Black Stainless Steel Bezel Tach/Hourmeter 3000 RPM; 50-304 pulses 11-28 VDC Bright Stainless Steel Bozel
ATHS-40-12 ATHS-40-12-A ATHS-40-12-B ATHS-40-12-C	Black Stainless Steel Bezel SAE Bright Stainless Steel Bezel SAE Black Stainless Steel Bezel
Alternator Signal	Tachometer 3000 RPM; 3 - 27 pulses 11-28 VDC
ATA-40-12	Bright Stainless Steel Bezel
ATA-40-12-A	Black Stainless Steel Bezel
ATA-40-12-B	SAE Bright Stainless Steel Bezel
ATA-40-12-C	SAE Black Stainless Steel Bezel
Alternator Signal	Tach/Hourmeter 4000 RPM; 3 - 27 pulses 11-28 VDC
ATHA-40-12	Bright Stainless Steel Bezel
ATHA-40-12-A	Black Stainless Steel Bezel
ATHA-40-12-B	SAE Bright Stainless Steel Bezel
ATHA-40-12-C	SAE Black Stainless Steel Bezel
ATHA-40-12-A	Black Stainless Steel Bezel
Ignition Signal Ta	ich/Hourmeter 4000 RPM; 4, 6 or 8 cylinder 11-28 VDC
ATHI-40-12-A	Black Stainless Steel Bezel

Optional Power Input Convertor

ATVC12/24 24 VDC to 12 VDC Converter

